

# BELZONA STOPS THE LEAKS ON HVAC TUBES


ID: 57

Industry: *Chemical & Petrochemical*  
Application: *VPF-Valves, Pipes and Fittings*  
Substrate: *Copper*  
Products: *\* Belzona®1111 (Super Metal) ,*

Customer Location: *Petrochemical Plant in Texas, U.S.A.*  
Application Date: *1991*

## Problem

*Leaking coolant*



## Photograph Descriptions

- \* An area was cut to gain access to the leaking pipe ,
- \* Leak stopped with Belzona® 1111 (Super Metal) ,

## Application Situation

Tube in HVAC coil

## Application Method

Application was carried out in accordance with Belzona Know-How Leaflet VPF-11a.

## Belzona Facts

After six years the repair is still in place.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve