

LIVE WATER LEAK CLAMPED WITH BELZONA



ID: 5704

Industry: General Industry
Application: VPF-Valves, Pipes and Fittings
Substrate: Steel Pipe
Products: * Belzona 1111 (Super Metal) ,

Customer Location: Hospital, Northern Texas, USA
Application Date: 2011

Problem

The hot water line was leaking from an expansion tank to the 2" line. The supply of hot water could not be shut off since it fed water to the emergency room.



Photograph Descriptions

- * Leaking pipe cleaned ,
- * Clamp ready to go ,
- * Application of Belzona 1111 ,
- * Clamp installed ,

Application Situation

Hot water line at a hospital

Application Method

A clamp was fabricated at a machine shop. The clamp had a threaded drain and matched threaded fittings. Belzona 1111 was applied to secure clamp to the hot water line.

Belzona Facts

This saved a major disruption to the hospital's emergency room. There was no alternative solution except replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve