

Make Hay While the Sun Shines

ID: 576

Industry: General Industry
Application: MPT-Mechanical Power Transmission

Customer Location: Farmer - Kansas U.S.A.
Application Date: July 2005

Substrate: Rubber
Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,

Problem

Tire was damaged but cords still in good condition. No replacement available.



Photograph Descriptions

- * Damaged tire. ,
- * All loose rubber removed from tire. ,
- * Release agent was applied to a mold. Belzona® 2211 was applied to the tire and mold. ,
- * The tire repaired. ,

Application Situation

Damaged obsolete U.S. Royal 5.50-16 implement tread tire from J.I. Case 140w hay baler.

Application Method

Application was carried out in accordance with a modified version of Belzona® Know-How System Leaflet MPT-10.

Belzona Facts

A wider tire would not fit the space between the baler and the tire. No manufacturer makes this size tire. A taller tire would cause an uneven hay pickup situation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024