

BELZONA GIVES NEW LIFE TO GROCERY STORE FLOOR



ID: 5772

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma-Quartz) ,
* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Grocery Store, Northern Texas, USA
Application Date: 2014

Problem

Receiving floor at a grocery store was so rough that groceries were falling off the pallets.



Photograph Descriptions

- * Preparation completed and conditioned with Belzona 4911 ,
- * Mixing station ,
- * Application in progress ,
- * Completed application ,

Application Situation

Damaged floor

Application Method

The floor was ground and conditioned with Belzona 4911 to prepare the surface for application. Then, 1/4 of Belzona 4111 was applied to level the floor.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

The application was started in the evening and ready for service by the first delivery. A previous product had failed within months.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

| | |
|----------------|---------------------------|
| ISO 9001:2015 | Belzona products are |
| FS 695214 | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality |
| EMS 695213 | Management System. |

www.belzona.com

