

LEAKING VENT SEALED WITH BELZONA

ID: 5773

Industry: Buildings & Structures

Customer Location: Buildings and Structures, Northern Texas, USA

Application: RPA-Roof Problem Areas

Application Date: 2013

Substrate: Tar and gravel roof

Products: * Belzona 3121 (MR7) ,

Problem

A roof vent was installed, but ponding water leaked through the black mastic roof sealer.



Photograph Descriptions

- * Newly installed vent ,
- * Prepared area ,
- * Fabric being applied ,
- * Completed application ,

Application Situation

Leaking vent

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. The surface was prepared by scraping away the gravel. Then, Belzona 3121 was applied with fabric to seal the duct.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



The roof was leaking in the production area from the vent. It was sealed the day before it rained, saving a production shutdown.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

