

# LEAKING VENT SEALED WITH BELZONA

ID: 5773

Industry: *Buildings & Structures*

Customer Location: *Buildings and Structures, Northern Texas, USA*

Application: *RPA-Roof Problem Areas*

Application Date: 2013

Substrate: *Tar and gravel roof*

Products: *\* Belzona 3121 (MR7) ,*

## Problem

*A roof vent was installed, but ponding water leaked through the black mastic roof sealer.*



## Photograph Descriptions

- \* Newly installed vent ,
- \* Prepared area ,
- \* Fabric being applied ,
- \* Completed application ,

## Application Situation

Leaking vent

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. The surface was prepared by scraping away the gravel. Then, Belzona 3121 was applied with fabric to seal the duct.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

The roof was leaking in the production area from the vent. It was sealed the day before it rained, saving a production shutdown.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

