BONDING SUPPORT PADS WITH BELZONA

ID: 578

Industry: Oil & Gas Customer Location: National Oil Co. - U.A.E.

Application: VPF-Valves, Pipes and Fittings Application Date: 2004

Substrate: Steel

Products: * Belzona® 1121 (Super XL-Metal),

Problem

Corrosion and wear of pipes in area of supports caused by the constant thermal expansion and contraction.









Photograph Descriptions

- * The working environment,
- * Bond area on pipeline grit blasted and Belzona® 1121 applied to wet out the surface,
- * Wear pad strapped into place and exuded material being faired off,
- * Completed application with pipe sat on support ,

Application Situation

Oil pipeline crossing desert from oil field to marine terminal

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-15.

Belzona Facts

Extended working life of Belzona® 1121 allows pads to be bonded effectively in the high desert temperatures. Over 300 pads have to be bonded to the pipeline.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve