

BELZONA REPAIRS HOLE ON SCUM TANK


ID: 5827

Industry: *Water / Wastewater*
Application: *HEX-Heat Exchangers*
Substrate: *Steel*
Products: ** Belzona 1161 (Super UW-Metal) ,*
** Belzona 9111 (Cleaner Degreaser) ,*

Customer Location: *Toronto, ON, Canada*
Application Date: *November 2014*

Problem

Hole caused by corrosion.



Photograph Descriptions

- * Prior to application ,
- * Preparation in progress ,
- * Application in progress ,
- * Completed application ,

Application Situation

Scum tank at a water pollution control plant.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet HEX-9 for repairing leaking pipework. The surface was prepared using a grinder to roughen the surface and Belzona 9111 was used to clean the area. Belzona 1161 was applied around the hole and then a piece of metal was placed over the product. Once the piece of metal is in place, Belzona 1161 was applied around the pipe in accordance with Belzona Instructions For Use.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Belzona Facts

Belzona 1161 bonds firmly to oily, wet and not fully prepared substrates. This system is simple to use and does not require specialist tools. By using Belzona 1161, the customer eliminated expensive replacement costs and minimized downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

