# BELZONA REPAIRS HOLE IN PROCESS KETTLE

ID: 5839

Industry: Food & Drink

Application: VPF-Valves, Pipes and Fittings

Substrate: Steel

Products: \* Belzona 1511 (Super HT-Metal),

\* Belzona 9111 (Cleaner Degreaser),

\* Belzona 9341 (Reinforcement Tape),

#### **Problem**

A hole in the weld seam due to corrosion.







Customer Location: Toronto, ON, Canada

Application Date: April 2013



## **Photograph Descriptions**

- \* Prior to application,
- \* Surface preparation in process,
- \* Completed application,
- \* Completed application,

## **Application Situation**

Process kettle at a food production plant.

#### **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-1 for rebuilding erosion-corrosion damage. The surface was prepared by using a hand grinder. Belzona 9111 was used to remove all of the dirt and grease from the surface. A layer of Belzona 1511 was applied to the area and Belzona 9341 was wrapped over the layer. Then, Belzona 1511 was applied once again in accordance with the Belzona Instructions For Use.

## **Belzona Facts**

The customer chose the Belzona solution since Belzona 1511 is a high temperature repair system that is designed for repairing metal and rebuilding equipment, while providing excellent corrosion protection. Under immersion, Belzona 1511 is suitable for

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com	
easily mixed and applied without the need for specialist tools and when cured is du	
applications up to 160°C (320°F). Belzona 1511 will not corrode and resists a wide re	

www.belzona.com