

BELZONA PROVIDES GREAT RETURN ON INVESTMENT

ID: 587

Industry: General Industry

Customer Location: Building Maintenance Company, South Texas USA

Application: MPT-Mechanical Power Transmission


Application Date: July 2005

Substrate: Steel

Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 9411 (Release Agent) ,

Problem

Worn shaft caused air handler to not operate effectively.



Photograph Descriptions

- * Worn area of air handler shaft ,
- * Surface preparation in-situ ,
- * Cured Belzona® 1111 ,
- * Air handler back in service ,

Application Situation

Air handler shaft

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

Belzona Facts

A new shaft would have cost \$2,700. For only \$200 worth of Belzona, the shaft was repaired in place and returned to service quickly. Literally tens of thousands of shafts have been repaired with Belzona providing our customers with a great return on investment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve