

BELZONA SEALS VALLEY GUTTERS

ID: 5887

Industry: *General Industry*
Application: *RPA-Roof Problem Areas*
Substrate: *Cast iron*
Products: ** Belzona 3131 (WG Membrane),*

Customer Location: *Manufacturing Plant, Scotland*
Application Date: *October 2014*

Problem

Full replacements of the gutter would have caused excessive disruption to the working areas below.



Photograph Descriptions

- * Length of gutters before surface preparation ,
- * Section of gutter showing build up of dirt & corrosion ,
- * Length of gutter coated ,
- * Standing water still an issue but the gutter is now leak free ,

Application Situation

Several valley gutters constructed from cast steel had begun to leak from the joints. These leaks were causing damage to the stored materials below.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

Belzona Facts

Belzona 3131, a liquid applied membrane, allowed the applicators to coat the existing substrate without removing large sections of

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

the roof. The Belzona 3131 system is flexible, which has allowed a long lasting repair over the problem joints where competitor materials had failed.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

