

# CONCRETE STEP REPAIR WITH BELZONA

ID: 5912

Industry: *Buildings & Structures*

Customer Location: *Building & Structures, North Carolina, USA*

Application: *FPA-Floor Problem Areas*

Application Date: *August 2015*

Substrate: *Concrete*

Products: *\* Belzona 4411 (Granogrip) ,  
\* Belzona 4111 (Magma-Quartz) ,*

## Problem

*Concrete steps were broken and deteriorating.*



## Photograph Descriptions

- \* Prior to application ,
- \* Preparing the surface by removing busted concrete ,
- \* Application of Belzona 4411 with some aggregate ,
- \* Completed application ,

## Application Situation

Concrete steps leading up to the entrance of building.

## Application Method

The old concrete was removed so that Belzona 4111 could fill in the spots. After the steps were smoothed over, Belzona 4411 was added with some aggregate.

## Belzona Facts

This entranceway was an eyesore and a trip hazard. The use of Belzona products provided a solution to both issues in a cost effective manner. This area is used frequently for special events, such as private catering and weddings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve