

# BEARING HOUSING REPAIR WITH BELZONA

ID: 593

Industry: *Water / Wastewater*  
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Watersupply company, Bulgaria*  
Application Date: *April, 2003*

Substrate: *Cast iron*  
Products: *\* Belzona® 1111 (Super Metal) ,*

## Problem

*Housing damage after bearing seized leading to increased clearance.*



## Photograph Descriptions

- \* Preparing surface ,
- \* Belzona® 1111 applied ,
- \* Housing with restored dimensions after machining ,

## Application Situation

Centrifugal pump bearing housing

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-6.

## Belzona Facts

Belzona solution saved both time and replacement cost allowing the equipment to be quickly returned to operation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve