

BELZONA REPAIRS BUTTERFLY VALVE SEALS

ID: 5941

Industry: General Industry
Application: VPF-Valves, Pipes and Fittings
Substrate: Natural Rubber
Products: * Belzona 2311 (SR Elastomer) ,
* Belzona 2911 (Elastomer QD Conditioner) ,

Customer Location: Cement Industry, Nashville, TN, USA
Application Date: February 2015

Problem

The customer uses a cyclone and piping to move cement from barges to silos. Eroded areas at the edge of the valve flappers were allowing small amounts of cement and air to escape around the edges and further eroding the natural rubber.



Photograph Descriptions

- * Erosion around the edges of the flapper ,
- * Erosion more obvious with flapper removed ,
- * Substrate cleaned and roughened, ready for conditioning ,
- * Completed application, ready to go back into service ,

Application Situation

Rubber gaskets on butterfly valves

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-1. The substrate was cleaned and roughened using a wire brush and a razor. The effect of the razor was to make dovetail like mechanical bonds. Belzona 2911 was used to condition the surface and allowed to dry for 30 minutes. The surface profile was rebuilt with Belzona 2311 using a Belzona applicator. Alternatively, a release agent could have been used on the flapper and the flapper could have been closed onto the still

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

wet Belzona 2311 to create a perfect seal.

Belzona Facts

Before the introduction of the Belzona solution, the customer was rebuilding the valves several times a year with new rubber gaskets that cost in excess of \$450.00 each. A single pack of Belzona 2311 enabled the customer to repair two gaskets, saving the customer over \$800.00 in total. Additionally, due to the abrasion resistance of Belzona elastomers, the customer gets a better service life out of the repairs than they were previously getting from new gaskets.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

