

BELZONA REPAIRS WASTEWATER PUMPS

ID: 598

Industry: Fluid Flow
Application: CEP-Centrifugal Pumps
Substrate: Cast iron
Products: * Belzona® 1341 (Supermetalgilde) ,

Customer Location: Large wastewater station, Egypt
Application Date: October 2000

Problem

Corroded diffuser, casings and impellers leading to low efficiency of the pumps.



Photograph Descriptions

- * Corroded casings ,
- * Corroded diffuser ,
- * Diffuser was coated ,
- * Impeller coating completed ,

Application Situation

Sulzer wastewater pumps (Five)

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

Belzona Facts

A total of five pumps were repaired saving \$700,000 - the price of new pumps. The pumps are still operating efficiently five years on. The pumps efficiency was raised 8% over the original performance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve