

LIVE LEAKS STOPPED AND SEALED WITH BELZONA

ID: 5982

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon Steel
Products: * Belzona 1212 ,

Customer Location: Tank Farm, Genova, Italy
Application Date: December 2015

Problem

The tanks suffered from severe corrosion up to through-wall defects with some live seawater leakage. It was only possible to stop the filtration plant for two hours.



Photograph Descriptions

- * General view of equipment ,
- * Detailed leakage ,
- * Plate bonded with Belzona 1212 ,
- * Close up of one of the bonded plates ,

Application Situation

Vertical sea water tanks in the activated carbon filtration plant of a coastal Hydrocarbon storage tank farm.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. Surface preparation was carried out using an MBX bristle blaster. Several metal plates were cold bonded with Belzona 1212 to cover thin wall and through wall defects.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

For a traditional weld repair, the customer would have to shut down the system and completely empty the tanks. Due to its surface-tolerant and fast-curing properties, Belzona 1212 was applied directly onto leaking tanks, bypassing the need for a shutdown. In a couple of hours the customer forgot about his problem.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

