

# LIVE LEAKS STOPPED AND SEALED WITH BELZONA

ID: 5982

Industry: *Chemical & Petrochemical*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Carbon Steel*  
Products: *\* Belzona 1212 ,*

Customer Location: *Tank Farm, Genova, Italy*  
Application Date: *December 2015*

## Problem

*The tanks suffered from severe corrosion up to through-wall defects with some live seawater leakage. It was only possible to stop the filtration plant for two hours.*



## Photograph Descriptions

- \* General view of equipment ,
- \* Detailed leakage ,
- \* Plate bonded with Belzona 1212 ,
- \* Close up of one of the bonded plates ,

## Application Situation

Vertical sea water tanks in the activated carbon filtration plant of a coastal Hydrocarbon storage tank farm.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. Surface preparation was carried out using an MBX bristle blaster. Several metal plates were cold bonded with Belzona 1212 to cover thin wall and through wall defects.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

## Belzona Facts

For a traditional weld repair, the customer would have to shut down the system and completely empty the tanks. Due to its surface-tolerant and fast-curing properties, Belzona 1212 was applied directly onto leaking tanks, bypassing the need for a shutdown. In a couple of hours the customer forgot about his problem.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

