# BELZONA ENSURES SAFETY ON WASTE MANAGEMENT TRUCKS

ID: 6000

Industry: Transport Customer Location: Montana, USA

Application: FPA-Floor Problem Areas Application Date: 2003

Substrate: Carbon Steel

Products: \* Belzona 1321 (Ceramic S-Metal),

\* Belzona 9211 (Supergrip Aggregate),

#### Problem

Workers rode on the back of moving trucks in adverse conditions which caused slippery footing. Safety was a big concern for these employees and, unfortunately, the factory installed steps were not sufficient. With more trucks to be put in service the solution needed to be replicated.









## **Photograph Descriptions**

- \* Surface preparation on full length stair treads,
- \* Non-Slip application completed on stair treads,
- \* Close up of an aggressive texture of the application,
- \* Steps installed on one of the garbage trucks,

### **Application Situation**

Garbage trucks. New vehicles had insufficient place at the back for workers to ride on safely. With more new trucks being put in service a safe solution needed to be found.

### **Application Method**

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-8 and Belzona Instructions For Use.

## **Belzona Facts**

Because of the excellent adhesion of Belzona 1321, it was the right material to hold Belzona 9211 in place. The product is also durable enough to withstand the cleaning of the steps in winter when snow and ice accumulated. The application to bulk stair

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA

www.helzona.com

orkers from personal injuries as well as the company from loss time and incidents.	