

# BELZONA REBUILDS CLARIFIER RUNNING TRACK

ID: 605

Industry: Water / Wastewater  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 4111 (Magma-Quartz),  
\* Belzona® 4911 (Magma TX Conditioner),

Customer Location: Sewage farm - Switzerland  
Application Date: 2003

## Problem

The wheels had caused between 2mm and 10mm wear to the concrete and were not running smoothly.



## Photograph Descriptions

- \* The clarifier track ,
- \* Conditioning the surface with Belzona® 4911 ,
- \* Rebuilding with Belzona® 4111 ,
- \* The finished track ,

## Application Situation

The running track alongside the clarifier

## Application Method

The track was rebuilt with Belzona® 4111 in accordance with Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)



Client chose Belzona over competitive system due to the total technical and application package put together by the Belzona Distributor.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

