

BELZONA REBUILDS CLARIFIER RUNNING TRACK

ID: 605

Industry: Water / Wastewater
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4111 (Magma-Quartz),
* Belzona® 4911 (Magma TX Conditioner),

Customer Location: Sewage farm - Switzerland
Application Date: 2003

Problem

The wheels had caused between 2mm and 10mm wear to the concrete and were not running smoothly.



Photograph Descriptions

- * The clarifier track ,
- * Conditioning the surface with Belzona® 4911 ,
- * Rebuilding with Belzona® 4111 ,
- * The finished track ,

Application Situation

The running track alongside the clarifier

Application Method

The track was rebuilt with Belzona® 4111 in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Client chose Belzona over competitive system due to the total technical and application package put together by the Belzona Distributor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

