

BELZONA GRIP SYSTEM OUTSTRIPS THE COMPETITION

ID: 6104

Industry: General Industry Customer Location: Pharmaceutical Company, UK

Application: FPA-Floor Problem Areas Application Date: 2005 - 2011

Substrate: Concrete

Products: * Belzona 4411 (Granogrip),

* Belzona 9231 (Surefoot Aggregate),

Problem

In 2005 the client had used Belzona 4411 on a series of external ramps to avoid slip incidents. As they later found adjacent areas that were undercover were also hazardous, they applied slip resistant adhesive tapes from a leading manufacturer. Unfortunately, the tapes would repeatedly fail and the loss of adhesion at the edges meant that they became trip hazards. These tapes would have to be reapplied every 12-18 months which was costly and disruptive. In the same 6-year period the Belzona materials had suffered only very minor damage, and so the client decided to extend the original application onto the undercover areas.







Photograph Descriptions

- * Original application revisited after 6 years,
- * Typical condition of tapes after 3 months ,
- * Belzona application extended in 2011,

Application Situation

Grip Coating for Ramps and Corridors.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

Belzona Facts

Belzona 4411 is solvent free and applied in a single coat, making the application very fast and ideal for sensitive areas. There are also a choice of colours and aggregates that can even survive heavy vehicle traffic. In 2016 the original areas were revisited and Belzona system continued to offer superb performance after 11 years continuous service.

www.belzona.com