BELZONA PROTECTS BOX GUTTERS

ID: 6111

Industry: Buildings & Structures Customer Location: Corporate Office, Teesside, UK

Application: RPA-Roof Problem Areas Application Date: 2013

Substrate: Plastic coated steel.

Products: * Belzona 3111 (Flexible Membrane),

Problem

The client was about to take possession of a newly constructed office block. However, the gutters were leaking at multiple points around the building and so they were refusing to take ownership until the roof was watertight. It was thought that the joints and drain points were at fault. The main contractor had tried to seal these with a bituminous coating, which was ineffective and so needed to be removed. Belzona were approached for a liquid applied solution that could be backed by a warranty.









Photograph Descriptions

- * Building front aspect,
- * Typical gutter on initial inspection,
- * Application of Belzona 3111 underway,
- * Application completed,

Application Situation

Plastic Coated Box Gutters.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-6 and RPA-8.

Belzona Facts

With so many people already working in the building, the water based Belzona 3111 system was ideal. A seamless flexible

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

membrane was applied al 320 metres. Once comple				
building.				
For more examples of Belzona K	now - How In Action, please vis	sit https://khia.belzona.com	1	

EMS 695213

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality Management System.

