

CHEMICAL BUILDING ROOF LEAK REPAIRED BY BELZONA 3111

ID: 6118

Industry: Chemical & Petrochemical
Application: RPA-Roof Problem Areas
Substrate: Concrete
Products: * Belzona 3111 (Flexible Membrane) ,
* ,
* ,

Customer Location: Chemical Company, Thailand
Application Date: November 2011

Problem

Leaks at roof joints allowed water to leak through causing damage to the chemicals stored below.



Photograph Descriptions

- * 1. Overall picture of the area that need to be repaired ,
- * 2. Belzona 3911 was applied ,
- * 3. First coat of Belzona 3111 incorporating Belzona 9311 Reinforcement sheet being applied ,
- * 4. Ongoing application of Belzona 3111 system to all roof joints ,

Application Situation

Chemical plant Roof

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet RPA-1 and RPA-2. The fully reinforced Belzona 3111 System was applied to bridge all joints on the roof.

Belzona Facts

Belzona 3111 provides excellent waterproofing and weatherproofing properties, ability to be applied at problem areas making it a cost effective solution on all sizes and types of roof.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve