

SWIMMING POOL FILTERS SEALED WITH BELZONA

ID: 6139

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Stainless steel
Products: * Belzona 1212 ,
* Belzona 5811DW2 (DW Immersion Grade) ,

Customer Location: Engineering Co, Slovenia
Application Date: May 2016

Problem

Filters were leaking due to defective welds



Photograph Descriptions

- * One of the filter drums ,
- * Belzona 1212 application to welds ,
- * Belzona 5811DW2 application ,
- * Completed application ,

Application Situation

Swimming pool filler drums.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-1 and TCC-4. Belzona 1212 was used to seal and smooth welds before applying Belzona 5811DW2 to provide overall corrosion protection.

Belzona Facts

Time to get back in service was of most importance. The Belzona system provided fast and long term repair and protection to old filter drums.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve