BELZONA PROTECTS NEW GLYCOL TANK

ID: 6146

Industry: General Industry Customer Location: Steel fabrication company, Scotland, UK

Application: TCC-Tanks and Chemical Containment Application Date: June 2016

Areas

Substrate: Mild steel

Products: * Belzona 5811 (Immersion Grade),

Problem

The tank is to contain Propylene Glycol so it was expected that in service corrosion would be experienced. A short turn around time was required for this tank to be returned to service within the customers expectations. Access was also restricted within the tank due to the internal furniture.









Photograph Descriptions

- * 1. Newly fabricated tank,
- * 2. Tank onsite, laid on its side,
- * 3. Coating underway,
- * 4. Completed application,

Application Situation

A newly fabricated tank for an industrial refrigeration system was in need of corrosion protection.

Application Method

Application was carried out in accordance with Belzona system Leaflet TCC-5.

Belzona Facts

The choice was between a corrosion resistant coating & fabricating a new tank out of stainless steel. Cost & lead time favored the coating option.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve