

# BELZONA REPAIRS CONCRETE AFTER BOLLARD REMOVAL

ID: 6190

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 4111 (Magma Quartz),

Customer Location: Shopping Centre, Bankstown, Australia  
Application Date: September 2004

## Problem

Removal of bollards left rough concrete substrate that was a trip hazard.



## Photograph Descriptions

- \* 1. Damaged concrete ,
- \* ,
- \* 2. Conditioner applied ,
- \* ,
- \* 3. Mixing Belzona 4111 ,
- \* ,
- \* 4. Applying Belzona 4111 ,

## Application Situation

Damaged concrete in 48 areas where bollards were removed

## Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-1.

## Belzona Facts

Ability to feather edge the Belzona 4111 enabled damaged areas to be quickly and simply levelled to eliminate trip hazard.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve