

BELZONA REPAIRS CONCRETE AFTER BOLLARD REMOVAL

ID: 6190

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona 4111 (Magma Quartz) ,*

Customer Location: *Shopping Centre, Bankstown, Australia*
Application Date: *September 2004*

Problem

Removal of bollards left rough concrete substrate that was a trip hazard.



Photograph Descriptions

- * 1.Damaged concrete ,
- * ,
- * 2.Conditioner applied ,
- * ,
- * 3.Mixing Belzona 4111 ,
- * ,
- * 4. Applying Belzona 4111 ,

Application Situation

Damaged concrete in 48 areas where bollards were removed

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-1.

Belzona Facts

Ability to feather edge the Belzona 4111 enabled damaged areas to be quickly and simply levelled to eliminate trip hazard.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024