

# BELZONA EXPANSION JOINT SEALANT FOR CORPORATE OFFICE

ID: 62

Industry: General Industry

Customer Location: Corporate offices of Tennessee power company

Application: FPA-Floor Problem Areas


Application Date: 1988

Substrate: Brick

Products: \* Belzona® 2221 (MP Fluid Elastomer),

## Problem

Existing sealant breaking loose, creating a pedestrian safety hazard.



## Photograph Descriptions

- \* The application was carried out with the in-house maintenance staff of the power company. Closed cell foam backer rod being inserted. ,
- \* Applying Belzona® 2221. ,
- \* Expansion joint sealed. ,

## Application Situation

Expansion joints on brick floors

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet FPA-6.

## Belzona Facts

All expansion joints were sealed with approximately \$30,000 in Belzona product. Nearly ten years after, they are still in good shape.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024