

# CURING CONCRETE CANCER WITH BELZONA

ID: 6206

Industry: Buildings & Structures

Customer Location: Apartment Complex, Gold Coast, Australia

Application: WPA-Wall Problem Areas

Application Date: May 2014

Substrate: Concrete

Products: \* Belzona 4111 (Magma Quartz),

## Problem

The original concrete was starting to degrade due to a combination of its prominent coastal location and incorrect positioning of the steel reinforcement during original construction. Carbonation had taken place causing corrosion of the reinforcement steel leading to concrete spalling.



## Photograph Descriptions

\* 1. Close up of the damaged balcony 2. Preparation underway 3. Application completed with temporary shuttering in place 4. The restored balcony ,

## Application Situation

Concrete balcony at a residential apartment complex

## Application Method

Application was carried out in accordance with Belzona System leaflet WPA-4. All areas of damaged concrete were removed back to a sound substrate after which the exposed reinforcement bars were also cleaned back to bright metal. The entire area was then coated with Belzona 4911 (TX Conditioner) before the area was rebuilt with Belzona 4111. Some temporary shuttering to help support the repair whilst it cured was installed. once cured, the shuttering was removed and the area painted to leave a pleasing aesthetic finish.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

## Belzona Facts

Belzona 4111 was chosen for its superior properties over conventional repair methods. Being a fast curing, non shrinking and impermeable layer that allows for a quick easy repair that also prevents a recurrence of the initial problem.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

