

# BELZONA RESTORES FRESH WATER COOLERS

ID: 622

Industry: *Marine*  
Application: *HEX-Heat Exchangers*  
Substrate: *Aluminium*  
Products: \* *Belzona® 5891 (HT Immersion Grade)* ,  
\* *Belzona® 1111 (Super Metal)* ,

Customer Location: *Italian Navy*  
Application Date: *September 2005*

## Problem

*Corrosion-erosion of inside vane, outside flanges and stud threads.*



## Photograph Descriptions

- \* Upper side of flange and valve seat ,
- \* Inside vane coated with Belzona® 5891 ,
- \* View of coupling flanges ,

## Application Situation

Fresh water coolers

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets HEX-2 and HEX-3.

## Belzona Facts

This type of cooler is no longer available, but with only 5000€ (\$6000) the problem was solved.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve