

BELZONA SAFETY FLOORING AROUND MIXER

ID: 6279

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 4411 (Granogrip) ,

Customer Location: Ceramics producer, Gliwice, Poland
Application Date: May 2011

Problem

The floor was covered with a rubber lining which was very slippery when Glycol was spilt on it. One worker had broken a foot after slipping on the floor.



Photograph Descriptions

- * 1. Grinding concrete floor ,
- * 2. Repair of damage and filling cavities with Belzona 4111 ,
- * 3. Application of Belzona 4411 ,
- * 4. General view of the floor after application of Belzona 4411 system ,

Application Situation

The floor lined with rubber lining around a mixer handling Glycol and other additives.

Application Method

The application was carried out in accordance with Belzona System Leaflet FPA-8. After removing rubber sheets and cleaning the concrete, Belzona 4111 was used to level the concrete before applying the Belzona 4411 non-slip system.

Belzona Facts

After application of Belzona 4411 floor is safe and there have been no more slips. Belzona 4411 provides a chemical resistant surface that makes clean-up of spills easy whilst providing a positive grip surface to prevent slips.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve