BELZONA RESTORES CORRODED PUMP HOUSING

ID: 628

Industry:	*General Industry*	Customer Location:	*Drinking water supplier, Lisbon region, Portugal*
Application:	*CEP-Centrifugal Pumps*	Application Date:	*November 2004*
Substrate:	*Cast iron*		
Products:	** Belzona® 1341 (Supermetalglide) ,*		

Problem

The pump had extensive corrosion.




Photograph Descriptions

* Corroded pump housing ,
* Corroded pump outlet ,
* Application of Belzona® 1341 ,
* Competed application ,

Application Situation

Horizontal split case centrifugal water distribution pump.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-5 & CEP-10.

Belzona Facts

Another, similar pump, had been coated with Belzona 6 years previously and recent inspection found it to be excellent condition so client had no hesitation in specifying Belzona again.

Copyright © Belzona International Limited 2024