

BELZONA RESTORES CORRODED PUMP HOUSING

ID: 628

Industry: *General Industry*

Customer Location: *Drinking water supplier, Lisbon region, Portugal*

Application: *CEP-Centrifugal Pumps*

Application Date: *November 2004*

Substrate: *Cast iron*

Products: ** Belzona® 1341 (Supermetalglide) ,*

Problem

The pump had extensive corrosion.



Photograph Descriptions

- * Corroded pump housing ,
- * Corroded pump outlet ,
- * Application of Belzona® 1341 ,
- * Completed application ,

Application Situation

Horizontal split case centrifugal water distribution pump.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-5 & CEP-10.

Belzona Facts

Another, similar pump, had been coated with Belzona 6 years previously and recent inspection found it to be excellent condition so client had no hesitation in specifying Belzona again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve