

BELZONA RESTORES CORRODED PUMP HOUSING

ID: 628

Industry: General Industry

Customer Location: Drinking water supplier, Lisbon region, Portugal

Application: CEP-Centrifugal Pumps

Application Date: November 2004

Substrate: Cast iron

Products: * Belzona® 1341 (Supermetalgilde) ,

Problem

The pump had extensive corrosion.



Photograph Descriptions

- * Corroded pump housing ,
- * Corroded pump outlet ,
- * Application of Belzona® 1341 ,
- * Completed application ,

Application Situation

Horizontal split case centrifugal water distribution pump.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-5 & CEP-10.

Belzona Facts

Another, similar pump, had been coated with Belzona 6 years previously and recent inspection found it to be excellent condition so client had no hesitation in specifying Belzona again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve