

BELZONA REPAIRS AND RESURFACES CRACKS IN CONCRETE SWIMMING POOL TANK


ID: 6284

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Concrete*
Products: ** Belzona 4111 (Magma Quartz) ,*
** Belzona 4911 (Magma TX Conditioner) ,*

Customer Location: *Coquitlam, BC*
Application Date: *April 2015*

Problem

Over a period of many years, the pool tank had developed in the region of 600 lineal feet of cracks. These had been repaired a number of times with limited success.



Photograph Descriptions

- * 1. Preparing cracks with a 1/4 inch diamond blade to depth of 1/2 inch. ,
- * 2. General view of various prepared cracks ,
- * 3. Cracks in the pool walls repaired in a similar fashion. ,
- * 4. Completed repairs in the diving tank. A total of more than 600 feet of cracks were rebuilt and resurfaced in this manner. ,

Application Situation

The concrete surfaces

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. The surface was prepared by using a 1/4 inch diamond blade. Belzona 4911 was applied and then Belzona 4111 was applied directly on to the conditioned surface with a float.

Belzona Facts

This was part of a major refurbishment project to rehabilitate this outdoor swimming pool. A previous similar project had performed extremely well with no maintenance problems over 5 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve