

BELZONA PROVIDES HYGIENIC WALLS

ID: 6285

Industry: General Industry

Customer Location: Medical equipment manufacturer,
Poland

Application: WPA-Wall Problem Areas

Application Date: April 2011

Substrate: Concrete/Plaster

Products: * Belzona 5111 (Ceramic Cladding),

Problem

The previous coating on the walls did not withstand ultraviolet radiation, and liquid disinfectants used to create a sterile environment.



Photograph Descriptions

* 1. The room under renovation 2.,3.,4. The walls coated with Belzona 5111 ,

Application Situation

Room in which sterile medical equipment is manufactured.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-2.

Belzona Facts

The high gloss Belzona 5111 resists the germicidal lamps and liquid disinfectant used to create a sterile environment. Belzona 5111 is ideal for creating hygienic wall surfaces.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve