

BELZONA PROVIDES HYGIENIC WALLS

ID: 6285

Industry: *General Industry*

Customer Location: *Medical equipment manufacturer, Poland*

Application: *WPA-Wall Problem Areas*

Application Date: *April 2011*

Substrate: *Concrete/Plaster*

Products: ** Belzona 5111 (Ceramic Cladding),*

Problem

The previous coating on the walls did not withstand ultraviolet radiation, and liquid disinfectants used to create a sterile environment.



Photograph Descriptions

* 1. The room under renovation 2.,3.,4. The walls coated with Belzona 5111 ,

Application Situation

Room in which sterile medical equipment is manufactured.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-2.

Belzona Facts

The high gloss Belzona 5111 resists the germicidal lamps and liquid disinfectant used to create a sterile environment. Belzona 5111 is ideal for creating hygienic wall surfaces.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve