

BELZONA SEALS ROOF SKYLIGHTS

ID: 6286

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Metal and polycarbonate*
Products: ** Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Office building, Silesia, Poland*
Application Date: *August 2011*

Problem

Large leaks occurred into offices below whenever it rains.



Photograph Descriptions

* 1. Skylight prepared for repair 2. Skylight after repair with Belzona 3111 3. Other sealed skylights 4. The roof in 2016 still good with Belzona 3111 ,

Application Situation

Corrugated sheet metal roof containing several skylights.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

Belzona Facts

Under the leaky roof was office manager. After application of Belzona 3111 for the first time the director was in a good mood! Belzona 3111 system is ideal for sealing around complex structures and bonds to a wide range of dissimilar substrates.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024