

# BELZONA SEALS ROOF SKYLIGHTS

ID: 6286

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Metal and polycarbonate*  
Products: *\* Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Office building, Silesia, Poland*  
Application Date: *August 2011*

## Problem

*Large leaks occurred into offices below whenever it rains.*



## Photograph Descriptions

\* 1. Skylight prepared for repair 2. Skylight after repair with Belzona 3111 3. Other sealed skylights 4. The roof in 2016 still good with Belzona 3111 ,

## Application Situation

Corrugated sheet metal roof containing several skylights.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

## Belzona Facts

Under the leaky roof was office manager. After application of Belzona 3111 for the first time the director was in a good mood! Belzona 3111 system is ideal for sealing around complex structures and bonds to a wide range of dissimilar substrates.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve