

# Belzona replaces indoor swimming pool expansion joints

ID: 6292

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete/ Tile*  
Products: *\* Belzona 2221 (MP Fluid Elastomer) ,*

Customer Location: *Tsawwassen, BC*  
Application Date: *August 2015*

## Problem

*Existing expansion joint material had failed.*



## Photograph Descriptions

- \* 1. Joint preparation completed by grinding the expansion joint slot to a clean dry porous finish ,
- \* 2. Joint masked off to ensure a neat and tidy finish ,
- \* 3. Application of Belzona 2221 ,
- \* 4. Completed application. ,

## Application Situation

The expansion joints of a pool

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-6. The surface was grinded to a clean dry porous finish, then Belzona 2221 was injected into the joint and allowed to settle and cure.

## Belzona Facts

This was the 3rd Belzona Elastomer expansion joint application. The original application completed in 2007 which it lasted for more than 8 years before it required any further maintenance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve