

BELZONA ROOF REPAIR, EIGHT YEARS AND HOLDING

ID: 63

Industry: *Power*
Application: *RPA-Roof Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 3111 (Flexible Membrane) ,*
** Belzona® 3911 (PSC Surface Conditioner) ,*

Customer Location: *Power Plant in Georgia*
Application Date: *1989*

Problem

Severe water leakage



Photograph Descriptions

- * Joints were leaking. ,
- * Belzona® 3111 applied 8 years ago and still preventing leakage. ,
- * Another view of the roof. ,

Application Situation

Expansion joints of slab roof above generators

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet RPA-1.

Belzona Facts

Eight years ago, approximately \$30,000 in Belzona product was used and solved the leakage problem. Based on the success, the plant recently purchased \$50,000 of material to fix the other side of the roof, basically to seal the joints and cracks in the concrete slab.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve