

QUARRY BELT REPAIR

ID: 634

Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Local Depot, Manchester UK*
Application Date: *June 2000*

Substrate: *Rubber*
Products: ** Belzona© 2311 (SR Elastomer) ,*

Problem

600mm (23inch) tear in the belt



Photograph Descriptions

* Large sand belt 600mm gash in the belt ,

Application Situation

Sand Belt

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

Belzona Facts

The belt performed well until the plants closing in 2004.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve

Copyright © Belzona International Limited 2025