Belzona Repair on Concrete Dam

ID: 6343

Industry: Buildings & Structures
Application: WPA-Wall Problem Areas

Substrate: Concrete

Products: * Belzona 4131 (Magma-Screed),

* Belzona 4141 (Magma-Build),

* Belzona 4911 (Magma TX Conditioner),

*

Problem

The damaged area is partially submerged and the entire area frequently wet from wave action. The dam has been declared a historic site so repair materials need to closely match the appearance of the original material.







Customer Location: Michigan, USA

Application Date: September 2016

Photograph Descriptions

- * 1. Damaged area at waterline,
- * 2. Work in process.,
- * 3. Finished repair,

Application Situation

The face of the 100 yr old concrete hydro dam was damaged at the waterline due to ice and wave action.

Application Method

A temporary dyke was created around the area needing repair. Compressed air was used to blow the standing water off the

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA

www.belzona.com

damaged area. The surface was prepped with chisels and a bristle blaster. Dust and loose debris were blown off. The 4911 was applied and the repair was made with 4141 to just below the desired finish level. Finally a coat of 4131 was applied to finish the work .

Belzona Facts

Belzona was chosen because of its rapid cure, non-shrink and superior adherence characteristics. Magma build was chosen due to the need to work without forms and Magma Screed for color and finish.

www.belzona.com