

BELZONA TROUGH REPAIR

ID: 635

Industry: *General Industry*

Customer Location: *Wire and cable manufacturer,
Manchester UK*

Application: *TCC-Tanks and Chemical Containment
Areas*

Application Date: *June 2002*

Substrate: *Aluminium*

Products: ** Belzona® 1341 (Supermetalglide) ,*

Problem

Micro-biological fouling occurring in trough due to temperature and pitting of substrate caused by chemicals used. This was causing health and safety issues and also leaks at joints.



Photograph Descriptions

- * The problem ,
- * The solution ,

Application Situation

Trough used to treat wire in drawing and coating process

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

Belzona gave a cost effective solution to the problem with the only other alternative being to replace all 320 meters (1050ft) of troughs. System still performing well 3 years on.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

