

BELZONA RESTORED DOCK STEPS GOOD AS NEW AFTER THREE DECADES

ID: 6368

Industry: Marine
Application: FPA-Floor Problem Areas
Substrate: Stone/Cement
Products: * Belzona 4111 (Magma-Quartz),
* Belzona 4151 (Magma-Resin),

Customer Location: Naval dock, La Spezia, Italy
Application Date: June, 1989

Problem

Access steps showed conspicuous signs of deterioration due to the aggressive marine environment and pedestrian traffic from workers over the decades.



Photograph Descriptions

* 1. Deteriorated steps 2. View of the edges during reconstruction 3. Application completed in June 1989 4. View of the same area in September 2016 ,

Application Situation

Dock was originally constructed in 1876. Access steps in the bottom of the basin required attention.

Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-1. The damaged area was high-pressure cleaned, manually scarified and rebuilt with Belzona 4111. Belzona 4151 was then applied on top in conjunction with marble chips.

Belzona Facts

Repair was performed in 1989 and was then inspected in September 2016. After 27 years of service the repaired steps showed no sign of degradation and were in perfect working order.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve