

BELZONA RENEWS 40 METRE VERTICAL EXPANSION JOINT

ID: 6420

Industry: Buildings & Structures
Application: WPA-Wall Problem Areas
Substrate: Concrete
Products: * Belzona 4141 (Magma-Build). ,
* Belzona 2211 (MP Hi-Build elastomer). ,
* Belzona 3111 (Flexible Membrane). ,

Customer Location: Industrial unit, Malta
Application Date: August 2014.

Problem

The existing joint material had failed resulting in a route for water ingress inside the building. Some of the offices could not be used because of this leak.



Photograph Descriptions

<div>
<table cellpadding="0" cellspacing="0" align="left">
<tbody>
<tr>
<td style="padding-top: 0cm; padding-right: 9.0pt; padding-bottom: 0cm; padding-left: 9.0pt;" align="left" valign="top">
<p class="MsoNormalCxSpFirst" style="background-image: initial; background-position: initial; background-size: initial; background-repeat: initial; background-attachment: initial; background-origin: initial; background-clip: initial;">1. Existing joint material removed and cleaned. ,
<p class="MsoNormalCxSpMiddle" style="background-image: initial; background-position: initial; background-size: initial; background-repeat: initial; background-attachment: initial; background-origin: initial; background-clip: initial;">2. Masking and conditioned. ,
<p class="MsoNormalCxSpMiddle" style="background-image: initial; background-position: initial; background-size: initial; background-repeat: initial; background-attachment: initial; background-origin: initial; background-clip: initial;">3. Application of Belzona 2211 Elastomer. ,
<p class="MsoNormalCxSpMiddle" style="background-image: initial; background-position: initial; background-size: initial; background-repeat: initial; background-attachment: initial; background-origin: initial; background-clip: initial;">

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



background-repeat: initial; background-attachment: initial; background-origin: initial; background-clip: initial;">4. Completed application. ,
</td>
</tr>
</tbody>
</table>
</div>

Application Situation

Failed expansion joint at industrial building

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet WPA-3 and WPA-9. The existing joint material was removed and the edges were rebuilt with Belzona 4141. Belzona 2211 was applied to seal the joint. To further seal and encapsulate the joint, bridging tape was applied over the expansion joint prior to the application of the Belzona 3111 system. This also provided an aesthetically pleasing finish.

Belzona Facts

Belzona 4141 provides a durable joint nosing, whilst Belzona 2211 provides a highly elastic long-term waterproof seal in the joint. The Client ordered two more expansion joint repairs after this one.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

