## BELZONA RESTORES AND PROTECTS GATE VALVE

ID: 6421

Industry: Mining & Quarrying Customer Location: Copper Minning Company, Bulgaria

Application: CEP-Centrifugal Pumps Application Date: April, 2015

Substrate: Carbon Steel

Products: \* Belzona 1311 (Ceramic R-Metal),

\* Belzona 1341 (Supermetalglide),

#### **Problem**

Strong corrosion and erosion on the inner surfaces of all 3 gate valves.









# **Photograph Descriptions**

- \* 1. General view of the valve before repair ,
- \* 2. After blasting and flange masking,
- \* 3. 1st coat of Supermetalglide applied,
- \* 4. Final view of the completed application ,

#### **Application Situation**

Three large gate valves for water transport from the local dam to the production area.

### **Application Method**

The application was carried out according to Belzona Know-How System Leaflet CEP-1 and CEP-3. The internal welds, pitting and damage were filled with Belozna 1311 then two coats of Belzona 1341 were applied.

#### **Belzona Facts**

Restoration of 3 valves was carried out within three days, which saved the customer time and money and also eliminated the need to buy new valves. Two months after the restoration of the gate valves, the client protected several pipes and elbows in the water

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



pment and repairs ar	e still in good workin	g condition.		

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality EMS 695213

Management System.



www.belzona.com