

BELZONA REPAIR BY ROPE ACCESS

ID: 654


Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Offshore Platform, Indonesia
Application Date: August 2005

Substrate: Carbon steel and Neoprene
Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,
* Belzona® 2121 (D&A Hi-Coat Elastomer) ,
* Belzona® 5831 (ST Barrier) ,

Problem

Damage on Neoprene coating and corrosion in splash zone.



Photograph Descriptions

- * Preparation of existing Neoprene ,
- * Rebuild and coating with Belzona® 2211 and Belzona® 2121 ,
- * Coating splashing zone with Belzona® 5831 ,
- * Complete application ,

Application Situation

8-inch diameter Neoprene coated Riser Pipe

Application Method

Application carried out in accordance with modified Belzona Know-How System Leaflet VPF-3. Existing Neoprene repaired and coated with Belzona® 2211 and Belzona® 2121. Splash zone protected with Belzona® 5831.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

Belzona systems chosen for their ease of application and Belzona® 5831 specifically for its surface tolerance and ability to cure in wet conditions.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

