

BELZONA PROTECTS CEMENT PACKING MACHINE STEEL PLATES

ID: 675

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Cement Works, Usje, Macedonia

Application Date: October 2004

Substrate: Steel

Products: * Belzona® 4811 (Magma AR Screed) ,

Problem

Deterioration of the steel plates and steel seats due to wear from the cement bags.



Photograph Descriptions

- * Cement packing machine. ,
- * Condition of the coated steel plate and steel seat after one year in service. (Experiment which shows no wear after one year). ,
- * Repaired seats and sheets. ,

Application Situation

Steel plates and steel seats of a cement packing machine.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-13.

Belzona Facts

Initially done as an experiment, the cheapest base metal was chosen and coated with Belzona. One year later the plates were inspected and were found have suffered from no wear at all. Belzona® 1812 would be expected to give similar results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

