

BELZONA PROTECTS CEMENT WORKS GEARBOX HOUSING


ID: 689

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona® 5811 (Immersion Grade),

Customer Location: Cement Works, Usje, Macedonia
Application Date: April 2005

Problem

Poor adhesion of old non-Belzona coating.



Photograph Descriptions

* Application situation The extent of the problem Prepared surface Finished application. ,

Application Situation

Gear box housing

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15.

Belzona Facts

Belzona's quick and effective solution was chosen for its ease of application and immediate availability. Very short down time meant that the customer saved a good deal of time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024